## ANNUAL REPORT\_ NON-EXEMPT ACTIVITIES **City of Cincinnati**

2016

THE TOHOWING PTO	jects were found to be exempt from Section 106	Date of	line 1105 110grammatic Agreement				
		Construction/ Age of					
	Duning at the continue						
	Project Location	Building when	Project Description Include				
	*Address for rehab or demo or new construction	building is part of	summary information about repairs, replacement,	National Projeton Chatus	D	Advance Effect Finding	D
Project Number	*Street name & cross streets for site work	project	reconstruction, new construction, or site work	National Register Status	Reasoning	Adverse Effect Finding	Reasoning
						No Effect No Advance Effect Advance	
	4.7	4050				No Effect, No Adverse Effect, Adverse	
example 1	1 Two Street	1960	rehab: storm doors, gutters, insulation	Listed, eligible, non-eligible	2 11 11 11 11 11 11 11	Effect	
	1640 Robinson Circle	1925	rebuild missing porch with sound materials.	Non-eliglbe	Building is not within an		
					elgibile historic district and not		
	and the state of t	1525	research missing person than secure materials.	68.26	eligible as individual listed		
					building		
					Building is not within an		
	408 Carmalt Street	1914	repair damamged osffit with aluminum or vinyl	Non-eliglbe	elgibile historic district and not		
					eligible as individual listed		
					building		
	2012 Ryan Ave	1908	repair damamged osffit with aluminum or vinyl	Non-eliglbe	OTR NR Historic District		
	3775 Heron Ave	Vacant Land	Construction of 25 SF homes	Non olialbo	Not within a Historic District or		
	3775 Heron Ave	Vacant Land	Construction of 25 SF nomes	Non-eliglbe	an elible area.		
			replace double hung windows with new vinyl				
			windows, remove and replace handrail system on		Building is not within an		
	3046 Gilbert Ave	1924	back porch, strip, refit and stabilize or reseal	Non-eliglbe	elgibile historic district and not		
			exterior and interior friction/impact surfaces, paint	J	eligible as individual listed		
			exterior, interior,		building		
			replace double hung windows with new vinyl		-		
			windows; remove and replace handrail system on				
	3830 Vine St	1923	balcony; cover balcony floor with carpet; strip, refit	Non-eligIbe	Duilding is not within an		
			and stabilize or reseal exterior and interior		Building is not within an		
					elgibile historic district and not		
			friction/impact surfaces, paint exterior, interior;		eligible as individual listed		
			repair damaged drywall in bathroom		building		